

# IRIS USB Reflasher

Software 11.15.1

## Table of Contents

1	Overview .....	3
2	Changes in thIS release .....	3

## I OVERVIEW

This document details IRIS USB Reflasher changes from software Version 11.15.0 to Version 11.15.1.

Please note – installing this release may not remove previous releases of the IRIS USB Reflasher. To prevent this, it is recommended that earlier version(s) of the IRIS USB Reflasher are uninstalled before this new version is installed.

Also note that this release installs a new USB driver called 'AddSecure'. This driver is shared with the IRIS Toolbox App, so if you install this version of USB Reflasher, you must install the latest IRIS Toolbox App as well.

## 2 CHANGES IN THIS RELEASE

ID	Details
<b>T39635</b>	Update with Edge VS5000 Version 4.17.7
<b>T39649</b>	Resolve an issue whereby terminals with a 3-part version string (e.g. NG terminals) do not get reflashed.